



Glen Ellyn Park District continues to seek resolution to fitness center roof leaks

Glen Ellyn, IL. - The Glen Ellyn Park District, along with all the contractors and architects involved in the construction of Ackerman Sports & Fitness Center, has been actively and aggressively working towards finding a proper solution to water leaks in the facility's roof.

The leaks were discovered by staff after the building's completion. Staff found the roof not to be weather tight as numerous leaks have been found, especially after a rain event.

According to Cory Atwell, Executive Director, "We have received a number of inquiries about our progress in this area. The full scope is still being evaluated at this time. Many solutions have been discussed at this point and engineers are evaluating and establishing a correct solution that will not only be immediate, but maintain the integrity of the roof and facility for many years in the future. We are hopeful for a solution soon."

The park district apologizes for any inconveniences the situation may have caused residents and ASFC patrons, and thanks them for their patience while this matter is being resolved as soon as possible.